

Alternator Decoupler Pulley

New Product Category

With TechSmart's new line of Alternator Decoupler Pulleys, you can replace a damaged pulley without spending time replacing the entire alternator assembly. Once installed, TechSmart's Alternator Decoupler Pulley will reduce stress on the belt drive system, leading to improved performance and a smoother, quieter ride. The direct-replacement parts cover over 3 million VIO.



G93005
 Ford Escape 2007-05
 Mazda Tribute 2006-05
 Mercury Mariner 2007-05
 VIO Over 170,000



G93007
 Volvo 2007-99
 VIO Over 560,000



G93011
 Audi 2013-02
 Volkswagen 2013-05
 VIO Over 580,000



G93012
 Audi 2013-02
 Volkswagen 2013-05
 VIO Over 580,000

Windshield Wiper Linkage

New Product Category

When windshield wiper linkage arms and bushings crack from wear and tear, they can prevent windshield wipers from functioning properly. To help you restore wiper function, TechSmart introduces a new line of Windshield Wiper Linkages for Hyundai and Kia applications. The direct-replacement linkages come as a complete assembly and cover over 6.5 million VIO.



Z99001
 Hyundai Accent 2005-00
 VIO Over 1.4 Million



Z99025
 Hyundai Sonata 2004-99
 Hyundai XG 300 2001
 Hyundai XG350 2005-02
 VIO Over 1.0 Million



Z99044
 Hyundai Accent 2011-06
 Kia Rio 2011-06
 Kia Rio5 2011-06
 VIO Over 390,000



Z99148
 Hyundai Santa Fe 2009-07
 VIO Over 290,000


Electronic Throttle Body



14 New SKUs Available

S20126
Toyota Corolla 2008-05
Toyota Matrix 2008-05
VIO Over 1.1 Million

HVAC Air Door Actuator



5 New SKUs Available

G04017
Audi TT Quattro 2001-98
Volkswagen Golf 2004-00
Volkswagen Jetta 2003-99
VIO Over 790,000

Engine Coolant Air Bleeder Valve



TechSmart® exclusive design features an extra hex nut for holding the valve in place with a wrench while bleeding the coolant, preventing damage to the valve

Z63011
Chrysler 2010-99
Dodge 2010-98
VIO Over 650,000

Ride Height Sensor



High-quality, direct replacement for damaged OE sensors

Z71073
Cadillac XLR 2009-04
Chevrolet Corvette 2011-04
VIO Over 200,000

Headlight Level Sensor



11 New SKUs Available

B71097
Lexus LS460 2013-07
Lexus LS600h 2013-08
VIO Over 100,000


Throttle Position Sensor Repair Kit



Replace just the failed sensor
Includes gasket and mounting hardware

I05002
Hyundai Santa Fe 2009-07
Kia Rondo 2012-07
VIO Over 160,000

Headlight Wiring Harness



With TechSmart, you no longer need to replace the entire HID ballast assembly when the harness fails

F90013
Lincoln Navigator 2005-03
Lincoln Town Car 2011-02
VIO Over 390,000

VVT Solenoid



High-quality replacement for clogged or burned out solenoids

L53002
GM 2010-02
VIO Over 2.7 Million