

THINK TECHSMART® FIRST

TechSmart® DISA Valve Repair Kits




The TechSmart® Kits come complete with a new flap, flap hinge, hinge pin, retaining clip, O-ring, and extractor screw.




The DISA Valve within the variable intake manifold on BMW vehicles raises the low and midrange torque and the top end power output. Over time, the OE flap becomes stripped, resulting in a rough idle, loss of power, and a DTC.

TechSmart® now offers high-quality repair kits for faulty DISA Valves on 2012-97 BMW vehicles. Save time and money by simply replacing the damaged flap and not the entire assembly.



F66001
DISA Valve Repair Kit
BMW 2000-97
VIO over 330,000



F66002
DISA Valve Repair Kit
BMW 2010-00
VIO over 670,000



F66003
DISA Valve Repair Kit
BMW 2006-01
VIO over 450,000



ARE YOU TECHSMART®?

