
MADE THICKER FOR TOUGHNESS.





When OE steering column shift tubes break at vulnerable stress points, the result is a labor-intensive repair, so you need a replacement that will last. TechSmart® Shift Tubes are twice as thick as the competition at the highest stress point, making them the stronger, longer-lasting choice. There's something to be said for a thick skin.

TechSmart[®] Steering Column Shift Tubes

- High-quality direct-fit replacement for failed original
- Meticulously engineered for toughness
- 3.2 mm at the highest stress point, twice as thick as the competition

The Evolution of Parts



Rhinoceroses have the thickest skin of any terrestrial mammal. The skin on their backs and flanks can be 1 inch thick.



TechSmartParts.com